

**Arkansas Department of Environmental Quality  
Hazardous Waste Division  
Technical Branch  
Trip Report**

|                             |  |
|-----------------------------|--|
| <b>Project</b>              | Former Cedar Chemical Facility   |
| <b>Location</b>             | West Helena, AR  |
| <b>Date</b>                 | Thursday, August 1, 2013   |
| <b>Time</b>                 | day trip   |
| <b>Reason</b>               | Observe Site Conditions  |
| <b>ADEQ personnel</b>       | Clay McDaniel CM   |
| <b>Facility personnel</b>   | Gary Hill – Harcross employee  |
| <b>Activity Summary</b>     | Gary accompanied with me as I inspected the facility   |
| <b>Action Items Summary</b> | <p>The soil pile from excavation of the sump is still located on the former Unit 4 foundation (see photo's 1 &amp; 2). It has been 519 days between when it was 1<sup>st</sup> discovered (ADEQ site visit on 3/1/2012) and this site visit. Bi-weekly status updates for the waste pile were requested in ADEQ letter dated 05/31/2012, but no updates have been submitted.</p> <p>Identified drum labeled hazardous waste (see photo # 3)</p> <p>The IDW (18 five-gallon buckets of purge water from the July 2010 sampling event, shown in photo #4) has not been disposed of. ADEQ letter dated 8/28/2012 provided procedures for proper disposal.</p> |
| <b>Follow-Up</b>            |  |

**Route to:**


| ADEQ personnel review | Initials | Date   |
|-----------------------|----------|--------|
| Jim Rigg              | JWR      | 8/6/13 |
| Annette Cusher        | AC       | 8/6/13 |
| Jay Rich              | JR       | 8-8-13 |


Enclosure: Photo Log



9459961


**Arkansas Department of Environmental Quality**  
**Official Photograph Log**


|  |  |
|--|--|
| <b>Soil Pile from Sump Excavation</b><br>(located on the former Unit 4 footprint)  |  |
| <b>Photo # 1</b>   | <b>Photographer:</b> Clay McDaniel, ADEQ <i>CM</i> |
| <b>Date:</b> August 1, 2013  | <b>Witness:</b> Gary Hill, Harcross                |
|  |  |

|  |  |
|--|--|
| <b>Soil Pile from Sump Excavation</b>  |  |
| <b>Photo # 2</b>   | <b>Photographer:</b> Clay McDaniel, ADEQ <i>CM</i> |
| <b>Date:</b> August 1, 2013  | <b>Witness:</b> Gary Hill, Harcross                |
|  |  |



# Arkansas Department of Environmental Quality Official Photograph Log

|   |  |
|---|--|
| <b>55-Gallon Drum Labeled Hazardous Waste</b>                                       |  |
| <b>Photo # 3</b>  | <b>Photographer:</b> Clay McDaniel, ADEQ <i>CM</i> |
| <b>Date:</b> August 1, 2013   | <b>Witness:</b> Gary Hill, Harcross                |
|  |  |

|  |  |
|--|--|
| <b>Investigative Derived Waste (purged groundwater)</b>                              |  |
| <b>Photo # 4</b>   | <b>Photographer:</b> Clay McDaniel, ADEQ <i>CM</i> |
| <b>Date:</b> August 1, 2013  | <b>Witness:</b> Gary Hill, Harcross                |
|  |  |